


N188MH

Engine Log

Date: 5/20/2026	Make: TCM	Model: TSIO-550-K	S/N: 1008046
Flight: 1113.3	Hobbs: 1409.8		

REMOVED ROCKER BOX COVER ON EXHAUST CYCL# 5. REPLACED ROCKER BOX COVER GASKET WITH NEW SILICONE GASKET P/N655705 AND TOURQUED TO 25 IN-LBS. SWAPPED LEFT AND RIGHT TIT TEMP SENSORS TO CONFIRM OPERATION. GROUND RAN ENGINE AND PERFORMED LEAK TEST, NO LEAKS FOUND. BOTH TIT SENSORS CHECKED OUT GOOD.
JOHN CHAVEZ A&P 3133342



Work accomplished at Santa Fe Aero Services, LLC. Reference work order # SO-26-0250